

City of San Antonio Draft Bid Tabulation

Opened: December 19, 2011			
For: Differential Component Parts and Rebuilt Exchange Units		Grande Truck Center	
6100000841		JF	4562 IH10 East
		San Antonio, TX 78219	
Item	Description	Estimated Annual Usage	
I.	Rockwell/Meritor Differential Component Parts (For Models Listed Below)		
A. Parts			Cost + 25%
	Percent of discount offered		Meritor
	Product identification (Mfr.)		Dealer
	Type of price schedule (dealer, jobber, etc.)		N/A
	Price schedule number		7/1/11
	Date of price schedule		Cost
	Price schedule column on which discount is based (i.e. distributor, net, wholesale, etc.)		
B. Manufacturer And Model Number			
	New Factory Assembly RD23160563	1	N/A
	Rebuilt Exchange Part Number RD23160563	1	\$4,641.92
C. Specified Items: (For Meritor RD23160563)			
	Bearing Kit Part Number Kit 4422	1	\$498.04
	Brand Offered		Meritor
	Part Offered		Kit 4422
	Rebuilt Kit Part Number Kit RR23160563	1	\$4,601.13
	Brand Offered		Meritor
	Part Offered		Kit RP23160A
	Ring & Pinion 5.63 Part Number B39672-1	1	\$755.11
	Brand Offered		Meritor
	Part Offered		B39672-1
	Differential Kit 2318		\$264.14
	Brand Offered		Meritor
	Part Offered		Kit 2318
	Differential Case Assembly Part Number A1-3235G2113	1	\$802.50
	Brand Offered		Meritor
	Part Offered		A1-3235G2113
D. Labor To Repair And Overhaul Meritor RD23160563			
	Labor Rate per Hour		\$75.00
E. Manufacturer And Model Number: Meritor RR23160563			
	New Factory Assembly Part Number RR23160563	1	N/A
	Rebuilt Exchange Part Number RR23160563	1	\$2,752.00
F. Specified Items: (For Meritor RR23160563)			
	Differential Kit Part Number Kit 2318	1	\$261.14
	Brand Offered		Meritor
	Part Offered		Kit 2318
	Rebuilt Kit Part Number RR23160	1	\$4,026.29
	Brand Offered		Meritor
	Part Offered		Kit RR23160

City of San Antonio Draft Bid Tabulation

Opened: December 19, 2011 For: Differential Component Parts and Rebuilt Exchange Units 6100000841			Grande Truck Center 4562 IH10 East
			JF
			San Antonio, TX 78219
Item	Description	Estimated Annual Usage	
	Ring & Pinion Part Number B40106-5 Brand Offered Part Offered	1	\$941.73 Meritor B40106-5
	Bearing Kit 4426 Brand Offered Part Offered	1	\$475.86 Meritor Kit 4426
	Differential Case Assembly A1-3235G2113 Brand Offered Part Offered	1	\$802.50 Meritor A1-3235G2113
G.	Specified Items: (For Meritor)		
	Caliper & Cap Assembly Part Number A1-3263M1157 Brand Offered Part Offered	1	\$873.78 Meritor A1-3263M1157
	Caliper & Cap Assembly Part Number A2-3263M1157 Brand Offered Part Offered	1	\$865.56 Meritor A2-3263M1157
	ABS Service Kit Part Number R955342 Brand Offered Part Offered	1	\$46.54 Meritor R955342
	Tie Rod End Part Number R230104 Brand Offered Part Offered	1	\$149.64 Meritor R230104
	Kit-Pad & LNG-AX Part Number Kit 15625PM Brand Offered Part Offered	1	\$244.58 Meritor Kit 15625PM
	Slack Adjuster Part Number R802463 Brand Offered Part Offered	1	\$78.99 Meritor R802463
H.	Labor To Repair And Overhaul Meritor RR23160563		
	Labor Rate per Hour		\$75.00
II.	Eaton Differential Component Parts (For Models Listed Below)		
A.	Parts		
	Percent of discount offered		Cost + 25%
	Product identification (Mfr.)		Eaton/Spicer
	Type of price schedule (dealer, jobber, etc.)		Dealer
	Price schedule number		N/A
	Date of price schedule		7/1/11
	Price schedule column on which discount is based (i.e. distributor, net, wholesale, etc.)		Cost

City of San Antonio Draft Bid Tabulation

Opened: December 19, 2011			Grande Truck Center 4562 IH10 East San Antonio, TX 78219
For: Differential Component Parts and Rebuilt Exchange Units			
6100000841		JF	
Item	Description	Estimated Annual Usage	
B.	New Assemblies		
	Eaton/Spicer DP463P Part Number 674953	1	\$6,390.78
	Eaton/Spicer RP463P Part Number 675512	1	\$4,311.11
C.	Specified Items: (for Eaton/Spicer DP463P Gear Ratio 5.29)		
	Rebuild Kit Part Number 122421	1	\$582.93
	Brand Offered Eaton		
	Part Offered 122421		
	Ring & Pinion 5.29 Part Number 124444	1	\$1,654.94
	Brand Offered Eaton		
	Part Offered 124444		
	Differential Case Kit Part Number 122417	1	\$414.40
	Brand Offered Eaton		
	Part Offered 122417		
	Differential Kit Part Number 119393	1	\$411.99
	Brand Offered Eaton		
	Part Offered 119393		
	Bearing Kit Part Number 122421	1	\$582.93
	Brand Offered Eaton		
	Part Offered 122421		
D.	Labor To Repair And Overhaul Eaton/Spicer DP463P		
	Labor Rate per Hour		\$75.00
E.	Specified Items: (for Eaton/Spicer RP463P Gear Ratio 5.29)		
	Rebuilt Kit Part Number 122424	1	\$344.49
	Brand Offered Eaton		
	Part Offered 122424		
	Ring & Pinion 5.29 Part Number 124445	1	\$1,637.51
	Brand Offered Eaton		
	Part Offered 124445		
	Differential Case Kit Part Number 122417	1	\$414.40
	Brand Offered Eaton		
	Part Offered 122417		
	Differential Kit Part Number 119393	1	\$411.99
	Brand Offered Eaton		
	Part Offered 119393		
	Bearing Kit Part Number 122424	1	\$344.49
	Brand Offered Eaton		
	Part Offered 122424		

City of San Antonio Draft Bid Tabulation

Opened: December 19, 2011 For: Differential Component Parts and Rebuilt Exchange Units 6100000841			Grande Truck Center 4562 IH10 East	
			JF	
			San Antonio, TX 78219	
Item	Description	Estimated Annual Usage		
F.	Labor To Repair And Overhaul Eaton/Spicer RP463P Gear Ratio 5.29			
	Labor Rate per Hour			\$75.00
III.	Eaton/Spicer Differential Component Parts (For Models Listed Below)			
A.	Parts			
	Percent of discount offered			Cost + 25%
	Product identification (Mfr.)			Eaton/Spicer
	Type of price schedule (dealer, jobber, etc.)			Dealer
	Price schedule number			N/A
	Date of price schedule			7/1/11
	Price schedule column on which discount is based (i.e. distributor, net, wholesale, etc.)			Cost
B.	Manufacturer And Model Number: Eaton/Spicer Model W230S			
	New Assembly Part Number 057CA108-7X	1		N/A
	Rebuilt Exchange Part Number 057CA108-7X	1		\$1,844.30
C.	Specified Items: (for Eaton W230S Gear Ratio 5.38)			
	Bearing Kit Part Number 474KS101	1		\$300.06
	Brand Offered			Eaton
	Part Offered			474KS101
	Rebuilt Kit Part Number 474KS101	1		\$300.06
	Brand Offered			Eaton
	Part Offered			474KS101
	Differential Case Assembly Part Number 493207C91	1		\$506.61
	Brand Offered			Eaton
	Part Offered			493207C91
	Differential Kit Part Number 472KS110-X	1		\$538.31
	Brand Offered			Eaton
	Part Offered			472KS110-X
	Ring & Pinion 5.38 Part Number 597253C91	1		\$1,556.38
	Brand Offered			Eaton
	Part Offered			597253C91
D.	Labor To Repair And Overhaul Eaton/Spicer W230S Gear Ratio 5.38			
	Labor Rate per Hour			\$75.00
IV.	Navistar International Differential Components Parts (For Models Listed Below)			
A.	Parts			
	Percent of discount offered			Cost + 25%
	Product identification (Mfr.)			Navistar/International
	Type of price schedule (dealer, jobber, etc.)			Dealer
	Price schedule number			N/A
	Date of price schedule			7/1/11
	Price schedule column on which discount is based (i.e. distributor, net, wholesale, etc.)			Cost

City of San Antonio Draft Bid Tabulation

Opened: December 19, 2011			
For: Differential Component Parts and Rebuilt Exchange Units		Grande Truck Center	
6100000841		JF	4562 IH10 East
Item	Description	Estimated Annual Usage	San Antonio, TX 78219
B.	Manufacturer And Model Number: Navistar International N400		
	New Assembly Part Number 1665235C92	1	\$4,899.25
	Rebuilt Exchange Part Number MN400F511	1	\$2,286.81
C.	Specified Items:		
	Ring & Pinion 5.11 Part Number 1665356C91	1	\$1,284.81
	Brand Offered		Navistar
	Part Offered		1665356C91
	Ring Gear Case Part Number 1665328C91	1	\$362.75
	Brand Offered		Navistar
	Part Offered		1665328C91
	Bearing Kit Part Number 1665333C91	1	\$536.64
	Brand Offered		Navistar
	Part Offered		401KS100-1X
D.	Labor To Repair And Overhaul Navistar International N400		
	Labor Rate per Hour		\$75.00
V.	Shop Labor Rate Per Hour For Removal Repair And Re-Installation of Units On Vehicles		
	Labor Rate per Hour		\$85.00
	Delivery		1 Day
	Mileage rate for same delivery day service		None/Per Mile
	Warranty		24 Months/100,000 miles on In-House Unit 12 Months-no mileage on all other units and parts
	Payment Terms		Net 30